


BASIC
WIRING DIAGRAM FOR GREDDY
BOOST CUT CONTROLER
AND
SPEED CUT DEFENCE

SAMPLE



+B 12 VOLT IGNITION
- GROUND SOURCE

SPD SPEED SENSOR INPUT

B/C BOOST CUT INPUT

RPM RPM PULSE SOURCE